

OSHA ▾ STANDARDS ▾ ENFORCEMENT TOPICS ▾ HELP AND RESOURCES ▾

Contact Us

FAQ

A to Z Index

English

Español

Inspection Detail

Case Status: VIOLATIONS UNDER CONTEST

Note: The following inspection has not been indicated as closed. Please be aware that the information shown may change, e.g. violations may be added or deleted. For open cases, in which a citation has been issued, the citation information may not be available for 5 days following receipt by the employer for Federal inspections or for 30 days following receipt by the employer for State inspections.

Inspection: 1372705.015 - The Herrick Corporation

Inspection Information - Office: Bakersfield District Office

Nr: 1372705.015	Report ID: 0950647	Open Date: 01/12/2019	
The Herrick Corporation 1900 Petrol Rd. Bakersfield, CA 93308		Union Status: Union	
SIC: NAICS: 238120/Structural Steel and Precast Concrete Contractors Mailing: P.O. Box 8429, Stockton, CA 95208			
Inspection Type:	Fat/Cat		
Scope:	Partial	Advanced Notice: N	
Ownership:	Private		
Safety/Health:	Safety	Close Conference: 07/17/2019	
		Close Case:	
Related Activity:	Type Accident	ID 1416417	Safety Health

Case Status: VIOLATIONS UNDER CONTEST

Violation Summary

	Serious	Willful	Repeat	Other	Unclass	Total
Initial Violations	3			2		5
Current Violations	3			2		5
Initial Penalty	\$47,810	\$0	\$0	\$840	\$0	\$48,650
Current Penalty	\$47,810	\$0	\$0	\$840	\$0	\$48,650
FTA Amount	\$0	\$0	\$0	\$0	\$0	\$0

Violation Items

#	ID	Type	Standard	Issuance	Abate	Curr\$	Init\$	Fta\$	Contest	LastEvent
1.	01001	Other	1514(D)	07/12/2019		\$420	\$420	\$0	07/15/2019	-

2.	01002	Other	1670(L)	07/12/2019		\$420	\$420	\$0	07/15/2019	-
3.	02001	Serious	1670(F)	07/12/2019	07/24/2019	\$22,500	\$22,500	\$0	07/15/2019	-
4.	03001	Serious	1670(B)(19)	07/12/2019		\$8,435	\$8,435	\$0	07/15/2019	-
5.	04001	Serious	1710(Q)	07/12/2019	07/24/2019	\$16,875	\$16,875	\$0	07/15/2019	-

Accident Investigation Summary

Summary Nr: 112806.015			Event: 01/12/2019			Employee Falls From Steel Structure And Is Killed				
At 2:32 p.m. on January 12, 2019, an employee had welded a steel post to the uppermost beam on a steel structure. The employee was wearing a deteriorated safety retractable system that had not been removed from service. During the fall, the fall arrest system failed and the employee was killed. The employee fell 48 feet to the ground.										
Keywords: welding, equipment failure, fall protection, fall										
	Inspection				Degree	Nature	Occupation			
1	1372705.015				Fatality	Other	Structural metal workers			

UNITED STATES DEPARTMENT OF LABOR

Occupational Safety and Health Administration
200 Constitution Ave NW
Washington, DC 20210
☎ 800-321-6742 (OSHA)
TTY
www.OSHA.gov

FEDERAL GOVERNMENT

White House
Severe Storm and Flood Recovery Assistance
Disaster Recovery Assistance
DisasterAssistance.gov
USA.gov
No Fear Act Data
U.S. Office of Special Counsel

OCCUPATIONAL SAFETY AND HEALTH

Frequently Asked Questions
A - Z Index
Freedom of Information Act
Read the OSHA Newsletter
Subscribe to the OSHA Newsletter
OSHA Publications
Office of Inspector General

ABOUT THE SITE

Freedom of Information Act
Privacy & Security Statement
Disclaimers
Important Website Notices
Plug-Ins Used by DOL
Accessibility Statement