

Inspection Detail

Case Status: VIOLATIONS UNDER CONTEST

Note: The following inspection has not been indicated as closed. Please be aware that the information shown may change, e.g. violations may be added or deleted. For open cases, in which a citation has been issued, the citation information may not be available for 5 days following receipt by the employer for Federal inspections or for 30 days following receipt by the employer for State inspections.

Inspection: 1372705.015 - The Herrick Corporation

Inspection Information - Office: Bakersfield District Office

Nr: 1372705.015	Report ID: 0950647	Open Date: 01/12/2019
The Herrick Corporation 1900 Petrol Rd. Bakersfield, CA 93308		Union Status: Union
SIC: NAICS: 238120/Structural Steel and Precast Concrete Contractors Mailing: P.O. Box 8429, Stockton, CA 95208		
Inspection Type: Fat/Cat	Scope: Partial	Advanced Notice: N
Ownership: Private	Safety/Health: Safety	Close Conference: 07/17/2019
Related Activity: Type	ID	Safety
Accident	1416417	Health

Case Status: VIOLATIONS UNDER CONTEST

Violation Summary

	Serious	Willful	Repeat	Other	Unclass	Total
Initial Violations	3			2		5
Current Violations	3			2		5
Initial Penalty	\$47,810	\$0	\$0	\$840	\$0	\$48,650
Current Penalty	\$47,810	\$0	\$0	\$840	\$0	\$48,650
FTA Amount	\$0	\$0	\$0	\$0	\$0	\$0

Violation Items

#	ID	Type	Standard	Issuance	Abate	Curr\$	Init\$	Fta\$	Contest	LastEvent
1.	01001	Other	1514(D)	07/12/2019		\$420	\$420	\$0	07/15/2019	-
2.	01002	Other	1670(L)	07/12/2019		\$420	\$420	\$0	07/15/2019	-
3.	02001	Serious	1670(F)	07/12/2019	07/24/2019	\$22,500	\$22,500	\$0	07/15/2019	-
4.	03001	Serious	1670(B)(19)	07/12/2019		\$8,435	\$8,435	\$0	07/15/2019	-
5.	04001	Serious	1710(Q)	07/12/2019	07/24/2019	\$16,875	\$16,875	\$0	07/15/2019	-

Accident Investigation Summary

Summary Nr: 112806.015

Event: 01/12/2019

Employee Falls From Steel Structure And Is Killed

At 2:32 p.m. on January 12, 2019, an employee had welded a steel post to the uppermost beam on a steel structure. The employee was wearing an Ultra-Safe brand safety retractable lanyard and harness. During the fall, the fall arrest system failed and the employee was killed. The employee fell 48 feet to the ground.

Keywords: welding, equipment failure, fall protection, fall

Inspection	Degree	Nature	Occupation
1 1372705.015	Fatality	Other	Structural metal workers